



Government of Tripura
Office of the Sub-Divisional officer
PWD (R&B), Dharmanagar Sub-Division
Dharmanagar, North Tripura.

Dated : 02/05/2026

Place: Dharmanagar

No. F. 30.151/ PWD/ SD/DMR/ 68

To
The Principal,
Shiksha Bhavan Montessori school
Shibbari Road, Baruakandi
Dharmanagar, North Tripura.

Ref.: Prayer for Issuance of Building Safety certificate. (Your office letter) Dated, 29th April 2026

Subject: Submission of Report on Building safety certificate.


Sir,

In reference to the above, a thorough inspection was conducted by the concerned authority i.e; PWD (R&B), Dharmanagar Sub-Division and a report on the same has been prepared as directed and is enclosed herewith.

It may kindly be noted that the findings in the report are based on visual inspection (eye estimation).

The same is submitted for your kind perusal and further necessary action.

Yours faithfully,


Sub-Divisional Officer
Dharmanagar Sub-Division, PWD (R&B)
Dharmanagar, North Tripura.

Enclosed:

1. Building Safety Certificate.

Copy To:

1. The Sub-Divisional Clerk, PWD (R&B), Dharmanagar Sub-Division, Dharmanagar, North Tripura - for information and record.

MANAGER

SHIKSHA BHAVAN MONTESSORI SCHOOL

Sub-Divisional Officer
Dharmanagar Sub-Division, PWD (R&B)
Dharmanagar, North Tripura.

Shiksha Bhavan Montessori School

Principal

Annexure -D

BUILDING SAFETY CERTIFICATE

No.:

Dated: 02/05/2026

It is certified that the existing building Siksha Bhavan Montessori School..... (name of the building or premises) at Shibbari Road, Baruakandi (Dharmanagar, North Tripura)..... (address) is having block(s)/floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floor(s) in the Block	1 no. (RCC framed structure with GCI Roofing)	1 no. (RCC framed structure with GCI Roofing)	3 nos. (2 floors are RCC roofed & 3 rd floor is GCI Roofed)	1 no. (RCC framed structure with GCI Roofing)	2 nos. (1 st floor is RCC roofed & 2 nd floor is GCI Roofed)
-Year of Construction-	2014	2015	-RCC framed structure -Year of Construction- 2018	-Year of Construction- 2020	-RCC framed structure -Year of Construction- 2023

The building is owned by Siksha Bhavan Montessori School..... (name of the Institution) have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Public Works Department (PWD), Dharmanagar (North Tripura) on 30/04/2026 in the presence of Mr. Subhankar Sen, Manager, Siksha Bhavan Montessori School, Mission Road, Dharmanagar, Tripura(N)..... (name and addresses of the Manager/ Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 02/05/2026 for a period of 5 years in accordance with rules and subject to compliance of the specific conditions as appended:

1. In case any addition/ alteration or expansion and modification to these buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
2. In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
3. These buildings can be safely occupied for normal use if the minor maintenance is carried out as per the recommendations of the undersigned up to 5(three) years (indicate up to which it can be used).

Issued on 02/05/2026 at Dharmanagar by SDO PWD (R&B)

Signature with Seal: _____


Name: Gautam P. S. D. (PWD)

Designation: SDO PWD, Dharmanagar

Name & Address of Department/Office: Public works Department
(PWD complex, Mission Road)

MANAGER

SIKSHA BHAVAN MONTESSORI SCHOOL

Siksha Bhavan Montessori School

Principal